

# Get out Breakdown

Get out Saturday 12<sup>th</sup>:

These times are provisional but should give an idea of the day.

**Saturday 12<sup>th</sup>: 09:00 – 18:00**

**09:00 Arrive at venue and get personal tools ready**

Tools Needed:

Quad Spanner/ Adjustable spanner

Allan Keys

Multitool

Hard Hat

LX Tape

Sharpie

Any tool drop prevention you have

**09:10 Strip speakers and remove XLR and power cabling**

Steps:

1. Disconnect all cabling from speaker
2. Disconnect speaker from drop bar then place speaker out of way of other workers
3. Work your way along the truss removing the XLR from the truss then repeat for the power cables
4. Take these cables to RS1 to begin sorting

**10:30 Strip XLR for cue lights + remove cue lights**

Tools required:

Tape

Hard Hat

Steps:

1. Start at one cue light and remove it and place within the cue light container
2. Slowly work your way around the truss to remove the cue light XLR
3. Take these cables to RS1 to begin sorting

## **11:00 Strip 16A and CAT5**

Tools Required:

n/a

Steps:

1. Disconnect the CAT5 from the desk and wind it back up into its loom.
2. Disconnect the 16A from the rubber boxes and coil then take to RS1
3. Return the rubber boxes to LX

## **12:00 Strip OP,SM and Sound 2 desk**

Steps:

1. Strip power cabling and re-case SQ5, UR4D, Soft-cue System and AR2412
2. Coil any cabling and take to RS1 for sorting
3. Return any Sound 2 items to Sound Cupboard box
4. Take receivers and place with UR4D

## **12:30 Sort Cabling in RS1**

## **12:50 Take kit to RS2 Doors for Van run**

## **13:00 Van Run?**

## **18:00 – Definite finish time**