

Stage Department Aftershow Checklist



Aftershow

- Once House is Clear
 - All fly floor breaks are on (expect chasing bars)
 - E-Stop on motor control
 - E-Stop on Automation

End of Day

- Clear Dias of Safety Curtain Line
 - Unlock Dias front and pull to edge of stage
 - Once Iron line is clear, drop Safety Curtain

Complete