

Hard Masking points

1	H.M	-7355	2115
2	H.M	-5655	2115
3	H.M	-7955	3775
4	H.M	-5655	3775
5	H.M	-8005	7923
6	H.M	-5655	7923
7	H.M	5655	2115
8	H.M	7355	2115
9	H.M	5655	3775
10	H.M	7955	3775
11	H.M	5655	7923
12	H.M	8005	7923

Soft Masking points

1	S.M.	-7957	674
2	S.M.	-7957	2146
3	S.M.	-4982	2146
4	S.M.	-8066	2413
5	S.M.	-8066	3884
6	S.M.	-5091	3885
7	S.M.	7957	674
8	S.M.	4982	2146
9	S.M.	7957	2146
10	S.M.	8066	2413
11	S.M.	5091	3885
12	S.M.	8066	3884

Automation points

1	Auto	-7897	5452
2	Auto	-181	5452
3	Auto	7602	5477

Front of House truss

1	FoH	-2260	-4124
2	FoH	2293	-4121