







SR Points List


Show	The Speculator		
Created By	Darren Wilson		
Date	12/10/2020	Version No.	V1


No.	Hoist Label	Location	X	Y		Type
27	FOH Load Arrest	House Left	-1750	-7735		Load Arrest
28	FOH Truss	House Left	-2000	-7735		Load Guard 500kg
29	LX Ladder 2	DSL	-6954	250		Hemp
30	Soft Leg 2 Return	DSR	-7500	840		Hemp
31	Bar Pick Up (7)	MSR	-6800	2020		Hemp
32	Hard Masker 2 On	DSR	-4950	2100		Hemp
33	Hard Masker 2 Off	DSR	-6650	2100		Hemp
34	LX Ladder 2	DSR	-6954	2150		Hemp
35	Soft Leg 2 On	DSR	-4800	2200		Hemp
36	Soft Leg 2 Off	DSR	-7150	2200		Hemp
37	LX Ladder 4	MSR	-6954	2620		Hemp
38	Soft Leg 4 Return	MSR	-7500	3250		Hemp
39	Bar Pick Up (13)	MSR	-6800	4400		Hemp
40	LX Ladder 6	USR	-7100	4400		Hemp
41	Hard Masker 4 On	MSR	-4300	4464		Hemp
42	Hard Masker 4 Off	MSR	-6050	4464		Hemp
43	LX Ladder 4	MSR	-6954	4500		Hemp
44	Soft Leg 4 On	MSR	-4800	4600		Hemp
45	Soft Leg 4 Off	MSR	-7150	4600		Hemp
46	LX Ladder 6	USR	-7100	6250		Hemp
47	Hard Masker 6 (Ground) On	USR	-3700	6418		Brace
48	Hard Masker 6 (Ground) Off	USR	-5420	6418		Brace
49	Soft Leg 6 On	USR	-5100	6500		Hemp
50	Soft Leg 6 Off	USR	-7500	6500		Hemp
51	Bar Pick Up (26)	USR	-7600	8840		Hemp
52	Bar Pick Up (27)	USR	-7600	9100		Hemp

Points List			
Show	The Speculator		
Created By	Darren Wilson		
Date	12/10/2020	Version No.	V1

No. Hoist Label	Location	X	Y	Symbol	Type
6 Hard Masker 1 On	DSL	4950	2100		Hard Masking (Hemp/ Brace)
7 Hard Masker 1 Off	DSL	6650	2100		
15 Hard Masker 3 On	MSL	4300	4464		
16 Hard Masker 3 Off	MSL	6050	4464		
21 Hard Masker 5 (Ground) On	USL	3700	6418		
22 Hard Masker 5 (Ground) Off	USL	5420	6418		
32 Hard Masker 2 On	DSR	-4950	2100		
33 Hard Masker 2 Off	DSR	-6650	2100		
41 Hard Masker 4 On	MSR	-4300	4464		
42 Hard Masker 4 Off	MSR	-6050	4464		
47 Hard Masker 6 (Ground) On	USR	-3700	6418		
48 Hard Masker 6 (Ground) Off	USR	-5420	6418		


4 Soft Leg 1 Return	DSL	7600	840		Soft Leg (Hemp)
9 Soft Leg 1 On	DSL	4800	2200		
10 Soft Leg 1 Off	DSL	7250	2200		
12 Soft Leg 3 Return	MSL	7600	3250		
18 Soft Leg 3 On	MSL	4800	4600		
19 Soft Leg 3 Off	MSL	7250	4600		
23 Soft Leg 5 On	USL	5100	6500		
24 Soft Leg 5 Off	USL	7600	6500		
30 Soft Leg 2 Return	DSR	-7500	840		
35 Soft Leg 2 On	DSR	-4800	2200		
36 Soft Leg 2 Off	DSR	-7150	2200		
38 Soft Leg 4 Return	MSR	-7500	3250		
44 Soft Leg 4 On	MSR	-4800	4600		
45 Soft Leg 4 Off	MSR	-7150	4600		
49 Soft Leg 6 On	USR	-5100	6500		
50 Soft Leg 6 Off	USR	-7500	6500		

6 Bar Pick Up (7)	DSL	6800	2020		Bar Pick Up (Hemp)
13 Bar Pick Up (13)	MSL	6800	4400		
25 Bar Pick Up (26)	USL	7600	8840		
26 Bar Pick Up (27)	USL	7600	9100		
31 Bar Pick Up (7)	MSR	-6800	2020		
39 Bar Pick Up (13)	MSR	-6800	4400		
51 Bar Pick Up (26)	USR	-7600	8840		
52 Bar Pick Up (27)	USR	-7600	9100		

5 LX Cable Pick (Bar 5)	DSL	6800	1000		LX Cable Tripe Pick Up (Hemp)
-------------------------	-----	------	------	---	-------------------------------

2 FOH Truss	House Right	2000	-7755		FOH Truss (Load Guard Chain Hoist)
28 FOH Truss	House Left	-2000	-7735		

1 FOH Load Arrest	House Right	1750	-7755		FOH Truss Fall Arrest
27 FOH Load Arrest	House Left	-1750	-7735		

3 LX Ladder 1	DSL	6954	250		LX Ladder (Drift)
8 LX Ladder 1	DSL	6954	2150		
11 LX Ladder 3	MSL	6954	2620		
14 LX Ladder 5	USL	7100	4400		
17 LX Ladder 3	MSL	6954	4500		
20 LX Ladder 5	USL	7100	6250		
29 LX Ladder 2	DSL	-6954	250		
34 LX Ladder 2	DSR	-6954	2150		
37 LX Ladder 4	MSR	-6954	2620		
40 LX Ladder 6	USR	-7100	4400		
43 LX Ladder 4	MSR	-6954	4500		
46 LX Ladder 6	USR	-7100	6250		