



































SL Points List			
Show	Covid Ballet 2020		
Head Fly Person	Darren Wilson		
Date	28/05/2020	Version No.	V2


No.	Hoist Label	Location	X	Y		Type
1	FOH LX Truss	Auditorium Right	1500	-7735		Load Guard Chain Hoist
2	FOH Load Arrest	Auditorium Right	1800	-7735		Fall Arrest
3	LX 1 Tripe Pick Up	DSL	6650	685		Hemp
4	Soft Leg	DSL Return	7582	856		Hemp
5	LX Boom Support	DSL	7015	970		Black Line
6	Bar Pick Up	CW 7 SL	7560	2142		Hemp
7	Hard Masking	DSL On	5650	2196		Hemp
8	Hard Masking	DSI Off	7400	2196		Hemp
9	Soft Leg	DSL On	4790	2272		Hemp
10	Soft Leg	DSL Off	7400	2272		Hemp
11	LX 2 Tripe Pick Up	DSL	6650	2392		Hemp
12	LX Ladder	DSL	7196	2409		Drift
13	LX Ladder Truss	DSL	7180	2572		Big Tow
14	Soft Leg	MSL Return	7582	2825		Hemp
15	LX Ladder	DSL	7196	3409		Drift
16	LX 3 Tripe Pick Up	MSL	7100	3740		Hemp
17	LX 3 Tripe Pick Up	MSL	7700	3740		Hemp
18	Hemp Bar	Mid	27	4094		Hemp
19	Hemp Bar	Long	4941	4094		Hemp
20	Bar Pick Up	Hemp Bar SL	7560	4094		Hemp
21	Hard Masking	MSL On	5650	4185		Hemp
22	Hard Masking	MSL Off	7400	4184		Hemp
23	Soft Leg	MSL On	4790	4261		Hemp
24	Soft Leg	MSL Off	7400	4261		Hemp
25	LX 4 Tripe Pick Up	USL	6650	4415		Hemp
26	LX Ladder	MSL	7196	4454		Drift
27	LX Ladder	MSL	7196	5454		Drift
28	Bar Pick Up	CW 15 SL	7560	5633		Hemp
29	Hard Masking	USL 1 On	5650	5795		Hemp
30	Hard Masking	USL 1 Off	7400	5795		Hemp
31	Soft Leg	USL On	5650	5884		Hemp
32	Soft Leg	USL Off	7574	5884		Hemp
33	LX Ladder	USL	7196	5913		Drift
34	LX 6 Tripe Pick Up	DSL	6650	5970		Hemp
35	LX Ladder Truss	USL	7180	6873		Big Tow
36	LX Ladder	USL	7196	6913		Drift
37	Hard Masking	USL 2 On	5650	7770		Hemo
38	Hard Masking	USL 2 Off	7400	7770		Hemo
39	Aperture Truss	SL ON	1826	8002		Load Guard Chain Hoist
40	Aperture Truss	SL OFF	5413	8002		Load Guard Chain Hoist
41	Bar Pick Up	CW 24 SL	6909	8205		Hemp


SR Points List


Show	Covid Ballet 2020		
Head Fly Person	Darren Wilson		
Date	28/05/2020	Version No.	V2


No.	Hoist Label	Location	X	Y	Icon	Type
42	FOH LX Truss	Auditorium Left	-1500	-7735		Load Guard Chain Hoist
43	FOH Load Arrest	Auditorium Left	-1800	-7735		Fall Arrest
44	Soft Leg	DSR Return	-7582	856		Hemp
45	LX Boom Support	DSR	-7015	970		Black Line
46	Bar Pick Up	CW 7 SR	-7470	2142		Hemp
47	Hard Masking	DSR On	-5650	2196		Hemp
48	Hard Masking	DSR Off	-7400	2196		Hemp
49	Soft Leg	DSR On	-4790	2272		Hemp
50	Soft Leg	DSR Off	-7400	2272		Hemp
51	LX Ladder	DSR	-7196	2409		Drift
52	LX Ladder Truss	DSR	-7180	2572		Big Tow
53	Soft Leg	MSR Return	-7582	2825		Hemp
54	LX Ladder	DSR	-7196	3409		Drift
55	Hemp Bar	Short	-4873	4094		Hemp
56	Bar Pick Up	Hemp Bar SR	-7470	4125		Hemp
57	Hard Masking	MSR On	-5650	4185		Hemp
58	Hard Masking	MSR Off	-7400	4184		Hemp
59	Soft Leg	MSR On	-4790	4261		Hemp
60	Soft Leg	MSR Off	-7400	4261		Hemp
61	LX Ladder	MSR	-7196	4454		Drift
62	LX Ladder	MSR	-7196	5454		Drift
63	Bar Pick Up	CW 15 SR	-7470	5633		Hemp
64	Hard Masking	USR 1 On	-5650	5795		Hemp
65	Hard Masking	USR 1 Off	-7400	5795		Hemp
66	Soft Leg	USR On	-5650	5884		Hemp
67	Soft Leg	USR Off	-7574	5884		Hemp
68	LX Ladder	USR	-7196	5913		Drift
69	LX Ladder Truss	USR	-7180	6873		Big Tow
70	LX Ladder	USR	-7196	6913		Drift
71	Hard Masking	USR 2 On	-5650	7770		Hemo
72	Hard Masking	USR 2 Off	-7400	7770		Hemp
73	Aperture Truss	SR ON	-1771	8002		Load Guard Chain Hoist
74	Aperture Truss	SR OFF	-5357	8002		Load Guard Chain Hoist
75	Bar Pick Up	CW 24 SR	-6909	8205		Hemp


Points List			
Show	Covid Ballet 2020		
Head Fly Person	Darren Wilson		
Date	28/05/2020	Version No.	V2

No. Hoist Label	Location	X	Y	Symbol	Type
7 Hard Masking	DSL On	5650	2196		Hard Masking (Hemp)
8 Hard Masking	DSI Off	7400	2196		
21 Hard Masking	MSL On	5650	4185		
22 Hard Masking	MSL Off	7400	4184		
29 Hard Masking	USL 1 On	5650	5795		
30 Hard Masking	USL 1 Off	7400	5795		
37 Hard Masking	USL 2 On	5650	7770		
38 Hard Masking	USL 2 Off	7400	7770		
47 Hard Masking	DSR On	-5650	2196		
48 Hard Masking	DSR Off	-7400	2196		
57 Hard Masking	MSR On	-5650	4185		
58 Hard Masking	MSR Off	-7400	4184		
64 Hard Masking	USR 1 On	-5650	5795		
65 Hard Masking	USR 1 Off	-7400	5795		
71 Hard Masking	USR 2 On	-5650	7770		
72 Hard Masking	USR 2 Off	-7400	7770		

4 Soft Leg	DSL Return	7582	856		Soft Leg (Hemp)
9 Soft Leg	DSL On	4790	2272		
10 Soft Leg	DSL Off	7400	2272		
14 Soft Leg	MSL Return	7582	2825		
23 Soft Leg	MSL On	4790	4261		
24 Soft Leg	MSL Off	7400	4261		
31 Soft Leg	USL On	5650	5884		
32 Soft Leg	USL Off	7574	5884		
44 Soft Leg	DSR Return	-7582	856		
49 Soft Leg	DSR On	-4790	2272		
50 Soft Leg	DSR Off	-7400	2272		
53 Soft Leg	MSR Return	-7582	2825		
59 Soft Leg	MSR On	-4790	4261		
60 Soft Leg	MSR Off	-7400	4261		
66 Soft Leg	USR On	-5650	5884		
67 Soft Leg	USR Off	-7574	5884		


6 Bar Pick Up	CW 7 SL	7560	2142		Bar Pick Up (Hemp)
20 Bar Pick Up	Hemp Bar SL	7560	4094		
28 Bar Pick Up	CW 15 SL	7560	5633		
41 Bar Pick Up	CW 24 SL	6909	8205		
46 Bar Pick Up	CW 7 SR	-7470	2142		
56 Bar Pick Up	Hemp Bar SR	-7470	4125		
63 Bar Pick Up	CW 15 SR	-7470	5633		
75 Bar Pick Up	CW 24 SR	-6909	8205		


18 Hemp Bar	Mid	27	4094		Hemp Bar (Hemp)
19 Hemp Bar	Long	4941	4094		
55 Hemp Bar	Short	-4873	4094		


3 LX 1 Tripe Pick Up	DSL	6650	685		LX Cable Tripe Pick Up (Hemp)
11 LX 2 Tripe Pick Up	DSL	6650	2392		
16 LX 3 Tripe Pick Up	MSL	7100	3740		
17 LX 3 Tripe Pick Up	MSL	7700	3740		
25 LX 4 Tripe Pick Up	USL	6650	4415		
34 LX 6 Tripe Pick Up	DSL	6650	5970		


1 FOH LX Truss	Auditorium Right	1500	-7735		FOH Truss (Load Guard Chain Hoist)
42 FOH LX Truss	Auditorium Left	-1500	-7735		

2 FOH Load Arrest	Auditorium Right	1800	-7735		FOH Truss Fall Arrest
43 FOH Load Arrest	Auditorium Left	-1800	-7735		

12 LX Ladder Truss	DSL	7180	2572		LX Ladder Truss (Big Tow Winch)
35 LX Ladder Truss	USL	7180	6873		
52 LX Ladder Truss	DSR	-7180	2572		
69 LX Ladder Truss	USR	-7180	6873		

12 LX Ladder	DSL	7196	2409		LX Ladder (Drift)
15 LX Ladder	DSL	7196	3409		
26 LX Ladder	MSL	7196	4454		
27 LX Ladder	MSL	7196	5454		
33 LX Ladder	USL	7196	5913		
36 LX Ladder	USL	7196	6913		
51 LX Ladder	DSR	-7196	2409		
54 LX Ladder	DSR	-7196	3409		
61 LX Ladder	MSR	-7196	4454		
62 LX Ladder	MSR	-7196	5454		
68 LX Ladder	USR	-7196	5913		
70 LX Ladder	USR	-7196	6913		

5 LX Boom 1SL Support	DSL	7015	970		LX Boom Support (Black Line)
45 LX Boom 1SR Support	DSR	-7015	970		

39 Aperture Truss	SL ON	1826	8002		Aperture Truss (Load Guard Chain Hoist)
40 Aperture Truss	SL OFF	5413	8002		
73 Aperture Truss	SR ON	-1771	8002		
74 Aperture Truss	SR OFF	-5357	8002		