

## RCS Risk Assessment Form

## ASSESSMENTS TO BE COMPLETED BEFORE STARTING NEW ACTIVITIES/TASKS

Task/Activity/Area: Persons At Risk: Reference: Initial Assessment Date: Employees/Students Innerspace fit up Innerspace project 2023 28/11/2023 Department: Risk Assessment WITHOUT Controls: Last Assessment Date: Risk Assessment WITH Controls: Ligthing Very High/High/Medium/Low Very High/High/Medium/Low Site/Location: Assessor: Paige MacGillivrav Reviewed By: Bischaltun New Athenaeum Theatre Signature: Signature:

Hazard Something with the potential to cause harm	Consequence The effect of that harm	Without Control Measures Ri (L x C)	Control Measures	With Control Measures Ri (L x C)
Moving lights getting kicked over when placed on floor	Falling over them resulting in brusing, lacerations, fractures or broken bones.	3x3=9	Put movers onto a raised steel deck, keeping them away from the edge. Put up a barrier to close it off from participants and also put visible tape to warn of a hazrd	1x2=2
Overhead work	See CPU001 (PTM general RA's on HS sharepoint)	See CPU001 (PTM general RA's on HS sharepoint)	See CPU001 (PTM general RA's on HS sharepoint)	See CPU001 (PTM general RA's on HS sharepoint)
Manual Handling	See CPU009 (PTM general RA's on HS sharepoint)	See CPU009 (PTM general RA's on HS sharepoint)	See CPU009 (PTM general RA's on HS sharepoint)	See CPU009 (PTM general RA's on HS sharepoint)
Working at Heights	See CPU010 (Working at Height RA's on HS sharepoint)	See CPU010 (Working at Height RA's on HS sharepoint)	See CPU010 (Working at Height RA's on HS sharepoint)	See CPU010 (Working at Height RA's on HS sharepoint)
Use of Tallescope	See CPU100 (Working at Height RA's on HS sharepoint)	See CPU100 (Working at Height RA's on HS sharepoint)	See CPU100 (Working at Height RA's on HS sharepoint)	See CPU100 (Working at Height RA's on HS sharepoint)
Use of Ladders and access equipment	See CPU103 (Working at Height RA's on HS sharepoint)	See CPU103 (Working at Height RA's on HS sharepoint)	See CPU103 (Working at Height RA's on HS sharepoint)	See CPU103 (Working at Height RA's on HS sharepoint)
Rigging lights - Lighting work NAT	See CPU101 (Lighting RA's on HS sharepoint)	See CPU101 (Lighting RA's on HS sharepoint)	See CPU101 (Lighting RA's on HS sharepoint)	See CPU101 (Lighting RA's on HS sharepoint)
	ł		1	

Tutor/Lecturer/Production Manager - Comments

FURTHER ACTIONS/MEASURES REQUIRED	Target Date:	Responsible Person:	Completion Date: