CATC KIT LIST

	CATC KIT LIST	
KIT	QUANTITY NOTES	PREPPED
	UPSTAGE STEEL DECK	
8X2 STEEL DECKS	4 FOR SIDE US PLATFORM	Χ
4X2 STEEL DECKS	1 FOR MID US PLATFORM	Χ
610MM LEGS WITH FEET	20 FOR US PLATFORM	STEVIE
	TREADS	
400MM TREADS	2 SIDE BAND TREADS	Χ
RATCHET STRAPS	2 SIDE BAND TREADS	Χ
	HARD MASKING	
HARD MASKING, SIZE TBC	2 FOR SIDE MASKING	Χ
BRACES	2 FOR HOLDING HARD MASKERS	X
PIN HINGES	6 TO ATTACH BRACES TO HARD MASKERS	X
4X25 WOOD SCREWS	36 FOR PIN HINGES	
STAGE WEIGHTS	4 WEIGHT FOR HARD MASKERS	X
	US BAR CLOTH AND SIGN	
M8 EYE BOLTS AND NYLOCKS	4 TO BE BOLTED THROUGH SIGNS	X
REGULAR WEDGE SOCKET	8 FOR HANGING SIGN	X
DOGS	8 FOR HANGING SIGN	Χ
500MM STROP	4 FOR HANGING SIGN	Χ
1 TONNE SHACKLES	4 FOR HANGING THE SIGN	Χ
10X8M RED CLOTH	1 BACK CLOTH	X
5000MM SCAFF	1 BACK CURTAIN SCAFF	X
6000MM SCAFF	1 BACK CURTAIN SCAFF	X
DOUGHTY SCAFF JOINER	1 CONNECT SCAFF TOGETHER ON BACK TRUSS	X
	TRUSS MOTORS	
1.5M STROP	2 FOR EXTRA POINTS ON-STAGE TRUSS	X
LOADGUARD 1/2 TONNE CHAIN MOTORS	2 TO GO ON FOH TRUSS	
BEAM CLAMPS	2 FOR EXTRA POINTS ON-STAGE TRUSS	X
500MM STROP	2 FOR ATTACHING LOADGUARD TO BEAM CLAMP	X
1 TONNE SHACKLES	2 FOR ATTACHING LOADGUARD TO BEAM CLAMP	Χ
H30V TRUSS	10M ON-STAGE TRUSS	Χ
	SOFT MASKING	
33M HEMP LINES	4 SOFT MASKING	
HEMP PULLEYS	2 SOFT MASKING	Χ
500MM STROP	2 SOFT MASKING	Χ
1 TONNE SHACKLE	2 SOFT MASKING	Χ
SCAFF TO HEMP JOINERS	0 SOFT MASKING	
6000MM SCAFF	2 SIDE MASKING	Χ
8X8 SOFT BLACKS	2 SOFT MASKING	Χ
	EXTRA	
HARD HAT LIGHT FROM CHANDLER	1 SAFETY	
HI-VIS	6 SAFETY	Χ
HARD HATS	6 SAFETY	Χ
	SNOW DROP	