PRODUCTION TECHNOLOGY MANAGEMENT

TECHNICAL STAGE DEPARTMENT

Tron Load In Schedule

Date	Time	Activity	Notes
29/05/2016	09:45	Crew Arrive on Site	
	10:00 - 10:15	Mark Motor Points	
		Unload TSM Truck of Truss	Motors first, kit boxes, truss then mesh
	10:15 - 10:30	Motors to be Hung	
		Continuing of truck unload	
	10:30 - 10:45	Truss to be floating	
	10:45 - 11:00	Hanging attachments to be attached	
	11:00 - 11:15	Section 1 to be Hung	Panels to be laid out prior
	11:15 - 11:30	Section 2 to be Hung	Panels to be laid out prior and attached to scaff
	11:30 - 11:45	Section 3 to be Hung	Panels to be laid out prior
	11:45 - 12:00	Structure Buffer Time	
	12:00 - 12:15	Structure Buffer Time	
	12:15 - 12:30	Build Screen	
	12:30 - 12:45	Hang Screen	
	12:45 - 13:00	Hang Border	
	13:00 - 13:15	Hanging Buffer Time	
	13:15 - 13:30	Masking Placement	
	13:30 - 13:45	Masking Fixing	
	13:45 - 14:00	Tidy	
	14:00	Finish	