





















































SL Points List			
Show	Dialouge Des Carmelites		
Head Fly Person	Darren Wilson		
Date	23/04/2020	Version No.	V3


No.	Hoist Label	Location	X	Y		Type
1	FOH Truss	FOH (SL)	2090	-3945		Load Guard Chain Motor
2	Fall Arrest	FOH (SR)	2394	-3945		Fall Arrest
3	German Masking DSL	DSL	8200	470		Hemp
4	TSD Truss SL 2	SL	1842	480		Load Guard Chain Motor
5	TSD Truss SL 1	SL	5437	480		Load Guard Chain Motor
6	Bar 5 Pick Up (SL)	Bar 5 SL	7555	1402		Hemp
7	Hard Masking SL (On Stage)	SL	5719	1619		Hemp
8	Hard Masking SL (Off Stage)	SL	7458	1619		Hemp
9	Hard Masking DSL	DSL	5640	1690		Hemp
10	Build Line DSL	SL	2400	2102		Hemp
11	German Masking USL	USL	8200	3190		Hemp
12	Hard Masking USL	USL	5640	3425		Hemp
13	Bar 12 Pick Up (SL)	Bar 12 SL	7555	3803		Hemp
14	Big Tow 1	DSL	1260	4384		Big Tow
15	Ladder 2 DS (SL)	SL	7415	4430		Hemp
16	LX Truss DSL	DSL	1260	4622		Dead Hang
17	Ladder 2 US (SL)	SL	7415	5430		Hemp
18	LX Truss USL	USL	1260	6061		Dead Hang
19	Big Tow 3	USL	1260	6113		Big Tow
20	Bar 18 Pick Up (SL)	Bar 18 SL	7555	6803		Hemp
21	Ladder 4 DS (SL)	SL	7415	6980		Hemp
22	Ladder 4 US (SL)	SL	7415	7980		Hemp
23	Bar 25 Pick Up (SL)	Bar 25 SL	7555	8570		Hemp
24	Build Line USL	SL	2400	8582		Hemp
25	Ladder 6 DS (SL)	SL	7415	8746		Hemp
26	Ladder 6 US (SL)	SL	7415	9746		Hemp


## SR Points List


<b>Show</b>	<b>Dialouge Des Carmelites</b>		
<b>Head Fly Person</b>	<b>Darren Wilson</b>		
<b>Date</b>	<b>23/04/2020</b>	<b>Version No.</b>	<b>V3</b>


No.	Hoist Label	Location	X	Y	Icon	Type
27	FOH Truss	FOH (SR)	-2094	-3945		Load Guard Chain Motor
28	Fall Arrest	FOH (SR)	-2389	-3945		Fall Arrest
29	German Masking (DSR)	DSR	-8100	470		Hemp
30	TSD Truss SR 3	SR	-1755	480		Load Guard Chain Motor
31	TSD Truss SR 4	SR	-5348	480		Load Guard Chain Motor
32	Bar 5 Pick Up (SR)	Bar 5 SR	-7445	1402		Hemp
33	Hard Masking SR (On Stage)	SR	-5750	1619		Hemp
34	Hard Masking SR (Off Stage)	SR	-7415	1619		Hemp
35	Hard Masking DSR	DSR	-5640	1690		Hemp
36	Build Line DSR	SR	-2400	2102		Hemp
37	German Masking USR	USR	-8100	3190		Hemp
38	Hard Masking USR	USR	-5640	3425		Hemp
39	Bar 12 Pick Up (SR)	Bar 12 SR	-7445	3803		Hemp
40	Big Tow 2	DSR	-1190	4384		Big Tow
41	Ladder 1 DS (SR)	SR	-7335	4430		Hemp
42	LX Truss DSR	DSR	-1179	4623		Dead Hang
43	Ladder 1 US (SR)	SR	-7335	5430		Hemp
44	LX Truss USR	USR	-1179	6062		Dead Hang
45	Big Tow 4	USR	-1190	6113		Big Tow
46	Bar 18 Pick Up (SR)	Bar 18 SR	-7445	6803		Hemp
47	Ladder 3 DS (SR)	SR	-7335	6980		Hemp
48	Ladder 3 US (SR)	SR	-7335	7980		Hemp
49	Bar 25 Pick Up (SR)	Bar 25 SR	-7445	8570		Hemp
50	Build Line USR	SR	-2400	8582		Hemp
51	Ladder 5 DS (SR)	SR	-7335	8746		Hemp
52	Ladder 5 US (SR)	SR	-7335	9746		Hemp


Points List			
Show	Dialouge Des Carmelites		
Head Fly Person	Darren Wilson		
Date	23/04/2020	Version No.	V3


Hoist Label	Location	X	Y	Symbol	Type
Big Tow 1	DSL	1260	4384		Automation Mother Grid (Big Tow Winches)
Big Tow 3	USL	1260	6113		
Big Tow 2	DSR	-1190	4384		
Big Tow 4	USR	-1190	6113		


LX Truss DSL	DSL	1260	4622		LX Truss Points (UNDER MOTHER GRID)
LX Truss USL	USL	1260	6061		
LX Truss DSR	DSR	-1179	4623		
LX Truss USR	USR	-1179	6062		


Hard Masking SL (On Stage)	SL	5719	1619		Masking & Bar Pick Up (Hemp)
Hard Masking SL (Off Stage)	SL	7458	1619		
Hard Masking DSL	SL	5640	1690		
Hard Masking USL	SL	5640	3425		
Hard Masking SR (On Stage)	SR	-5750	1619		
Hard Masking SR (Off Stage)	SR	-7415	1619		
Hard Masking DSR	SR	-5640	1690		
Hard Masking USR	SR	-5640	3425		
German Masking DSL	SL	8200	470		
German Masking USL	SL	8200	3190		
German Masking DSR	SR	-8100	470		
German Masking USR	SR	-8100	3190		
Bar 5 Pick Up (SL)	Bar 5 SL	7555	1402		
Bar 12 Pick Up (SL)	Bar 12 SL	7555	3803		
Bar 18 Pick Up (SL)	Bar 18 SL	7555	6803		
Bar 25 Pick Up (SL)	Bar 25 SL	7555	8570		
Bar 5 Pick Up (SR)	Bar 5 SR	-7445	1402		
Bar 12 Pick Up (SR)	Bar 12 SR	-7445	3803		
Bar 18 Pick Up (SR)	Bar 18 SR	-7445	6803		
Bar 25 Pick Up (SR)	Bar 25 SR	-7445	8570		

FOH Truss	FOH (SL)	2090	-3945		FOH Truss (Load Guard Chain Motor)
FOH Truss	FOH (SR)	-2094	-3945		

Fall Arrest	FOH (SL)	2394	-3945		FOH Truss Arrest (Fall)
Fall Arrest	FOH (SR)	-2389	-3945		

Ladder 2 DS (SL)	SL	7415	4430		LX Ladders (Hemp)
Ladder 2 US (SL)	SL	7415	5430		
Ladder 4 DS (SL)	SL	7415	6980		
Ladder 4 US (SL)	SL	7415	7980		
Ladder 6 DS (SL)	SL	7415	8746		
Ladder 6 US (SL)	SL	7415	9746		
Ladder 1 DS (SR)	SR	-7335	4430		
Ladder 1 US (SR)	SR	-7335	5430		
Ladder 3 DS (SR)	SR	-7335	6980		
Ladder 3 US (SR)	SR	-7335	7980		
Ladder 5 DS (SR)	SR	-7335	8746		
Ladder 5 US (SR)	SR	-7335	9746		

TSD Truss SL 1	SL	5437	480		TSD Truss (Load Guard Chain Motors)
TSD Truss SL 2	SL	1842	480		
TSD Truss SR 3	SR	-1755	480		
TSD Truss SR 4	SR	-5348	480		

Build Line DSL		2400	2102		Build Point (Hemp)
Build Line USL		2400	8582		
Build Line DSR		-2400	2102		
Build Line USR		-2400	8582		