

# Hypochondriac

## Automation Cue Sheet V-1

<u>Cue/State</u>	<u>Description</u>	<u>Axis</u>	<u>Position (mm)</u>	<u>Target</u>	<u>Speed (mmp/s)</u>	<u>Acc. (mmp/s)</u>	<u>Dec. (mmp/s)</u>	<u>Notes</u>
1	Wall OUT Truss IN	3+4 1+2	0 1400	7023 650	388 7950	200 200	200 200	Group 2 Dead 5 Group 1 Dead 2
3	Tension On Wires OUT	1+2	7950	8253	200	200	200	GP1 Dead 3
4	Argan Flies OUT	1+2	8253	11705	87	200	200	GP1 Dead 4 Time 40 Seconds
5	Argan IN	1+2	11705	7950	700	200	200	GP1 Dead 2
6	Truss OUT END	1+2	7950	14000	1000	200	200	GP1 Dead 1

RESET WALL FOR NEXT SHOW!!

\* Cue # 10 is programmed into the desk for if the actor cannot fly for reasons such as his harness becoming loose, and is same as Cue # 1 WALL OUT but without TRUSS IN.