


RCS Production Risk Assessment | Ballet 2017

Rigging FOH Truss



Significant Hazard		Who might be harmed?	Risk Factor (P x S)	Control Measures	Residual Risk (P x S)	Further Actions Necessary to Control risk	Further Action Review Date:
1	Tools/objects falling from height	Crew on deck.	3 x 5 (15)	All tools will be secured to body. All objects will be secured if possible or kept in closed pockets. All people on deck will wear hard hats and the orange flashing lights will be turned on. All rigging gear will be prepared ahead of time	1 x 5 (5)	Lanyards available in TSM NAT box.	2018-05-14
2	Manual handling hauling chain.	Crew on deck. Crew Hauling chain	4 x 3 (12)	All people involved in activity will have undergone RCS Manual Handling training and ladder safety training.	2 x 3 (6)		
3	Chain spill	People in auditorium	3 x 5 (15)	The chain will be checked visually by head of flies prior to each day.	1 x 5 (5)		
Assessment Compiled By:		Yesha Subotincic West			Date of assessment:		2017-05-19
Signature:					Further Action Review:		2018-05-14
Position:		Technical Stage Manager			RA Review Date:		
Assessment reviewed By:							
Reviewer Signature:							
Note: 5 x 5 Probability / Severity Matrix used							